

16-10-B Patterson Pump Repair and Bowl Assembly
 Becky Daves and Sharon Lytes
 December 1, 2015 at 3:00 p.m.

FGC Veterans Pump and Blower Repair
 David B. Cochran
 5105 Buffalo Avenue
 Jacksonville, FL 32206

Pump Repair & Supply
 John Spivey
 3349 South Bay Drive
 Jonesboro, GA 30236

Southeast Pump Specialist
 Cory Williams
 3317 Perkins Road
 Augusta, GA 30906

Bid on repair of Patterson 200 HP VT PUMP					
Transport to repair facility and back to the Aiken County PSA		A		\$2,200.00	\$450.00
Provide report on as found and shipped		A		\$200.00	\$300.00
Blast/Clean/Paint		A		\$1,500.00	\$2,400.00
Replace fasteners as required		A		\$600.00	\$575.00
Replace/Rework Pump Shaft				\$2,200.00	NA
Replace/Rework Line Shaft				\$2,230.00	\$5,800.00
Replace Bushings				\$5,500.00	\$3,790.00
Replace Shaft Couplings				\$1,800.00	\$3,275.00
Replace Lip Seals		A		\$400.00	\$325.00
Replace Packing Sleeve				\$1,500.00	\$990.00
Inspect/Repair Packing Gland				\$600.00	\$595.00
Replace Packing				\$800.00	\$210.00
Replace Gaskets		A		\$250.00	\$275.00
Assembly and Labor charges		A		\$3,800.00	\$4,950.00
Provide a complete repair report, including vibration analysis		A		\$200.00	\$1,950.00
Any additional parts and labor that may be required at an additional charge (Labor rate and % mark-up on parts)				\$85.00 per hour/15%	\$750.00
Cost of Pump Repair				\$14,680.00	\$26,635.00
				see 2nd pg for grand total	see 2nd pg for grand total
Any warranty given on work performed				One (1) year	12 Months parts/labor

16-10-B Patterson Pump Repair and Bowl Assembly Becky Dawes and Sharon Lyles December 1, 2015 at 3:00 p.m.	FGC Veterans Pump and Blower Repair David B. Cochran 5105 Buffalo Avenue Jacksonville, FL 32206	Pump Repair & Supply John Spivey 3349 South Bay Drive Jonesboro, GA 30236	Southeast Pump Specialist Cory Williams 3317 Perkins Road Augusta, GA 30906
Bid on repair of Patterson 200 HP VT Bowl Assembly			
Transport to repair facility and back to The Aiken County PSA			
Provide report on as found and shipped			
Blas/Clean/Paint			
Replace fasteners as required			
Repair/Replace Pump shaft			
Replace Bearings			
Replace Wear Rings			
Coat impeller with Epoxy			
Balance Impeller			
Replace Gaskets			
Assembly and Labor charges			
Provide a complete repair report, including vibration analysis			
Any additional parts and labor that may be required at an additional charge (Labor rate and % mark-up on parts)			
Any Warranty given on work performed			
Cost of Bowl Assembly			
Cost of Pump Repair			
Grand Total			

* Local Preference may apply. Nine (9) registered and suggested vendors were notified of the opportunity to submit bids. Three (3) were received. The bid was advertised in the Aiken Standard on November 9, 2015

Recommendation of the PSA Business Manager: Pump Repair & Supply

Signature: Mark Cook Date: 12/13/15

Approval/Disapproval of the County Administrator: Approved to Pump Repair and Supply

Signature: Clay Kalliam Date: 12/14/15